

```
<!DOCTYPE html>
<html lang="en">
<head>
  <meta charset="UTF-8">
  <meta name="viewport" content="width=device-width, initial-scale=1.0">
  <meta http-equiv="X-UA-Compatible" content="ie=edge">
  <title>Document</title>
</head>
<body>
  <script>
    let bigArray=[
      {
        "projectId": "Pj4419000005",
        "c1": 1,
        "c1str": "品质",
        "limit": 5,
        "value": 4,
        "overFlag": 0
      },
      {
        "projectId": "Pj4419000005",
        "c1": 1,
        "c1str": "品质",
        "c2": 101,
        "c2str": "环境品质风险",
        "limit": 5,
        "value": 4,
        "overFlag": 0
      },
      {
        "projectId": "Pj4419000005",
        "c1": 1,
        "c1str": "品质",
        "c2": 101,
        "c2str": "环境品质风险",
        "c3": 10101,
        "c3str": "热湿环境",
        "limit": 5,
        "value": 4,
        "overFlag": 0
      },
      {
        "projectId": "Pj4419000005",
        "c1": 1,
        "c1str": "品质",
        "c2": 101,
        "c2str": "环境品质风险",
        "c3": 10101,
        "c3str": "热湿环境",
        "c4": 1010101,
        "c4str": "室内温度过高",
        "limit": 5,
        "value": 4,
        "overFlag": 0
      },
    ],
```

```
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10101,
  "c3str": "热湿环境",
  "c4": 1010102,
  "c4str": "室内环境偏冷",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10101,
  "c3str": "热湿环境",
  "c4": 1010103,
  "c4str": "室内温度不均",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10101,
  "c3str": "热湿环境",
  "c4": 1010104,
  "c4str": "室内湿度偏大",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10101,
  "c3str": "热湿环境",
  "c4": 1010105,
  "c4str": "室内干燥",
  "limit": 5,
  "value": 4,
  "overFlag": 0
}
```

```
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10102,
  "c3str": "空气品质",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10102,
  "c3str": "空气品质",
  "c4": 1010201,
  "c4str": "甲醛超标",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10102,
  "c3str": "空气品质",
  "c4": 1010202,
  "c4str": "CO2超标",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10102,
  "c3str": "空气品质",
  "c4": 1010203,
  "c4str": "VOC超标",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
}
```

```
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10102,
  "c3str": "空气品质",
  "c4": 1010204,
  "c4str": "PM2.5超标",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10103,
  "c3str": "声环境",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10103,
  "c3str": "声环境",
  "c4": 1010301,
  "c4str": "噪音超标",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10103,
  "c3str": "声环境",
  "c4": 1010302,
  "c4str": "背景音乐缺失",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
```

```
"projectId": "Pj4419000005",
"c1": 1,
"c1str": "品质",
"c2": 101,
"c2str": "环境品质风险",
"c3": 10104,
"c3str": "光环境",
"limit": 5,
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10104,
  "c3str": "光环境",
  "c4": 1010401,
  "c4str": "照明中断",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10104,
  "c3str": "光环境",
  "c4": 1010402,
  "c4str": "照度不足",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10104,
  "c3str": "光环境",
  "c4": 1010403,
  "c4str": "装饰照明中断",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
```

```
"c1": 1,
"c1str": "品质",
"c2": 101,
"c2str": "环境品质风险",
"c3": 10104,
"c3str": "光环境",
"c4": 1010404,
"c4str": "照明过度",
"limit": 5,
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10104,
  "c3str": "光环境",
  "c4": 1010405,
  "c4str": "炫光",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10105,
  "c3str": "室内装修损坏",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10105,
  "c3str": "室内装修损坏",
  "c4": 1010501,
  "c4str": "地砖问题",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
```

```
"c1str": "品质",
"c2": 101,
"c2str": "环境品质风险",
"c3": 10105,
"c3str": "室内装修损坏",
"c4": 1010502,
"c4str": "墙皮问题",
"limit": 5,
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10105,
  "c3str": "室内装修损坏",
  "c4": 1010503,
  "c4str": "吊顶问题",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 101,
  "c2str": "环境品质风险",
  "c3": 10105,
  "c3str": "室内装修损坏",
  "c4": 1010504,
  "c4str": "广告灯箱问题",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 102,
  "c2str": "基础服务局部中断风险",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 102,
  "c2str": "基础服务局部中断风险",
```

```
"c3": 10201,
"c3str": "垂直交通系统故障",
"limit": 5,
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 102,
  "c2str": "基础服务局部中断风险",
  "c3": 10201,
  "c3str": "垂直交通系统故障",
  "c4": 1020101,
  "c4str": "电梯失效",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 102,
  "c2str": "基础服务局部中断风险",
  "c3": 10201,
  "c3str": "垂直交通系统故障",
  "c4": 1020102,
  "c4str": "电梯门关不上",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 102,
  "c2str": "基础服务局部中断风险",
  "c3": 10201,
  "c3str": "垂直交通系统故障",
  "c4": 1020103,
  "c4str": "电梯异响",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 103,
  "c2str": "设施故障或缺失风险",
  "limit": 5,
```



```
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 103,
  "c2str": "设施故障或缺失风险",
  "c3": 10301,
  "c3str": "家具问题",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 103,
  "c2str": "设施故障或缺失风险",
  "c3": 10301,
  "c3str": "家具问题",
  "c4": 1030101,
  "c4str": "家具故障",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 103,
  "c2str": "设施故障或缺失风险",
  "c3": 10302,
  "c3str": "盥洗间问题",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 103,
  "c2str": "设施故障或缺失风险",
  "c3": 10302,
  "c3str": "盥洗间问题",
  "c4": 1030201,
  "c4str": "马桶堵塞",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
}
```

```
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 103,
  "c2str": "设施故障或缺失风险",
  "c3": 10302,
  "c3str": "盥洗间问题",
  "c4": 1030202,
  "c4str": "洗手池故障",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 103,
  "c2str": "设施故障或缺失风险",
  "c3": 10303,
  "c3str": "污水系统问题",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 103,
  "c2str": "设施故障或缺失风险",
  "c3": 10303,
  "c3str": "污水系统问题",
  "c4": 1030301,
  "c4str": "污水系统溢水",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
  "c1str": "品质",
  "c2": 103,
  "c2str": "设施故障或缺失风险",
  "c3": 10304,
  "c3str": "车库设施故障",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 1,
```

```
"c1str": "品质",
"c2": 103,
"c2str": "设施故障或缺失风险",
"c3": 10304,
"c3str": "车库设施故障",
"c4": 1030401,
"c4str": "车库出入口闸机故障",
"limit": 5,
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30101,
  "c3str": "起火风险",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30101,
  "c3str": "起火风险",
  "c4": 3010101,
  "c4str": "电力输配起火",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
}
```

```
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30101,
  "c3str": "起火风险",
  "c4": 3010102,
  "c4str": "电力末端起火-强电专业",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30101,
  "c3str": "起火风险",
  "c4": 3010103,
  "c4str": "电力末端起火-弱电专业",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30101,
  "c3str": "起火风险",
  "c4": 3010104,
  "c4str": "电力末端起火-空调专业",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30101,
  "c3str": "起火风险",
  "c4": 3010105,
  "c4str": "电力末端起火-给排水专业",
  "limit": 5,
  "value": 4,
  "overFlag": 0
}
```

```
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30101,
  "c3str": "起火风险",
  "c4": 3010106,
  "c4str": "电力末端起火-消防专业",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30101,
  "c3str": "起火风险",
  "c4": 3010107,
  "c4str": "电力末端起火-安防专业",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30101,
  "c3str": "起火风险",
  "c4": 3010108,
  "c4str": "电力末端起火-其他专业",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30101,
  "c3str": "起火风险",
  "c4": 3010109,
  "c4str": "燃气起火",
  "limit": 5,
  "value": 4,
```

```
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30102,
  "c3str": "火灾蔓延风险",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30102,
  "c3str": "火灾蔓延风险",
  "c4": 3010201,
  "c4str": "逃生通道失效",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30102,
  "c3str": "火灾蔓延风险",
  "c4": 3010202,
  "c4str": "灭火设施失效",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30102,
  "c3str": "火灾蔓延风险",
  "c4": 3010203,
  "c4str": "逃生设施失效",
  "limit": 5,
  "value": 4,
  "overFlag": 0
}
```

```
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30102,
  "c3str": "火灾蔓延风险",
  "c4": 3010204,
  "c4str": "应急照明失效",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30102,
  "c3str": "火灾蔓延风险",
  "c4": 3010205,
  "c4str": "消防报警设施失效",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30102,
  "c3str": "火灾蔓延风险",
  "c4": 3010206,
  "c4str": "燃气报警设施失效",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 301,
  "c2str": "消防风险",
  "c3": 30102,
  "c3str": "火灾蔓延风险",
  "c4": 3010207,
  "c4str": "消防联动失效",
  "limit": 5,
  "value": 4,
```

```
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30201,
  "c3str": "消防政策合规",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30201,
  "c3str": "消防政策合规",
  "c4": 3020101,
  "c4str": "维护记录不全",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30201,
  "c3str": "消防政策合规",
  "c4": 3020102,
  "c4str": "设备状态异常",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
```



```
"c1str": "事故",
"c2": 302,
"c2str": "政策合规",
"c3": 30201,
"c3str": "消防政策合规",
"c4": 3020103,
"c4str": "作业人员不合规",
"limit": 5,
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30202,
  "c3str": "废气排放合规",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30202,
  "c3str": "废气排放合规",
  "c4": 3020201,
  "c4str": "维护记录不全",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30202,
  "c3str": "废气排放合规",
  "c4": 3020202,
  "c4str": "设备状态异常",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
```

```
"c2": 302,
"c2str": "政策合规",
"c3": 30203,
"c3str": "废水排放合规",
"limit": 5,
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30203,
  "c3str": "废水排放合规",
  "c4": 3020301,
  "c4str": "维护记录不全",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30203,
  "c3str": "废水排放合规",
  "c4": 3020302,
  "c4str": "设备状态异常",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30204,
  "c3str": "室内空气合规",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30204,
```

```
"c3str": "室内空气合规",
"c4": 3020401,
"c4str": "维护记录不全",
"limit": 5,
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30204,
  "c3str": "室内空气合规",
  "c4": 3020402,
  "c4str": "设备状态异常",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30205,
  "c3str": "作业人员合规",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30205,
  "c3str": "作业人员合规",
  "c4": 3020501,
  "c4str": "电力作业人员不合规",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 302,
  "c2str": "政策合规",
  "c3": 30205,
  "c3str": "作业人员合规",
```

```
"c4": 3020502,
"c4str": "电梯作业人员不合规",
"limit": 5,
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30301,
  "c3str": "困人",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30301,
  "c3str": "困人",
  "c4": 3030101,
  "c4str": "电梯困人",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30301,
  "c3str": "困人",
  "c4": 3030102,
  "c4str": "空间困人",
  "limit": 5,
  "value": 4,
  "overFlag": 0
}
```

```
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30301,
  "c3str": "困人",
  "c4": 3030103,
  "c4str": "设备困人",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30302,
  "c3str": "人员坠落",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30302,
  "c3str": "人员坠落",
  "c4": 3030201,
  "c4str": "暖通系统",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30302,
  "c3str": "人员坠落",
  "c4": 3030202,
  "c4str": "装饰系统",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
}
```

```
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30302,
  "c3str": "人员坠落",
  "c4": 3030203,
  "c4str": "土建",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30303,
  "c3str": "高空坠物",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30303,
  "c3str": "高空坠物",
  "c4": 3030301,
  "c4str": "高空物体砸落",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30303,
  "c3str": "高空坠物",
  "c4": 3030302,
  "c4str": "广告装饰坠落",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
```

```
"projectId": "Pj4419000005",
"c1": 3,
"c1str": "事故",
"c2": 303,
"c2str": "人身伤害",
"c3": 30304,
"c3str": "触电",
"limit": 5,
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30304,
  "c3str": "触电",
  "c4": 3030401,
  "c4str": "人员触电风险",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30305,
  "c3str": "机械伤害",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 303,
  "c2str": "人身伤害",
  "c3": 30305,
  "c3str": "机械伤害",
  "c4": 3030501,
  "c4str": "机械绞伤",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
```

```
"c2": 303,
"c2str": "人身伤害",
"c3": 30305,
"c3str": "机械伤害",
"c4": 3030502,
"c4str": "尖锐划伤",
"limit": 5,
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30401,
  "c3str": "停水风险",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30401,
  "c3str": "停水风险",
  "c4": 3040101,
  "c4str": "生活用水大面积中断",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30401,
  "c3str": "停水风险",
  "c4": 3040102,
```



```
"c4str": "中水大面积中断",
"limit": 5,
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30401,
  "c3str": "停水风险",
  "c4": 3040103,
  "c4str": "生活热水大面积中断",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30401,
  "c3str": "停水风险",
  "c4": 3040104,
  "c4str": "直饮水大面积中断",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30401,
  "c3str": "停水风险",
  "c4": 3040105,
  "c4str": "水景用水大面积中断",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30401,
  "c3str": "停水风险",
```

```
"c4": 3040106,
"c4str": "喷灌用水大面积中断",
"limit": 5,
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30401,
  "c3str": "停水风险",
  "c4": 3040107,
  "c4str": "娱乐用水大面积中断",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30402,
  "c3str": "停电风险",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30402,
  "c3str": "停电风险",
  "c4": 3040201,
  "c4str": "大面积停电风险",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30403,
  "c3str": "断网风险",
  "limit": 5,
```

```
"value": 4,
"overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30403,
  "c3str": "断网风险",
  "c4": 3040301,
  "c4str": "大面积断网风险",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30404,
  "c3str": "断冷风险",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30404,
  "c3str": "断冷风险",
  "c4": 3040401,
  "c4str": "大面积停止供冷",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30405,
  "c3str": "断热风险",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
}
```

```

{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30405,
  "c3str": "断热风险",
  "c4": 3040501,
  "c4str": "大面积停止供热",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30406,
  "c3str": "断气风险",
  "limit": 5,
  "value": 4,
  "overFlag": 0
},
{
  "projectId": "Pj4419000005",
  "c1": 3,
  "c1str": "事故",
  "c2": 304,
  "c2str": "重点基础服务中断",
  "c3": 30406,
  "c3str": "断气风险",
  "c4": 3040601,
  "c4str": "大面积停止供气",
  "limit": 5,
  "value": 4,
  "overFlag": 0
}
]
let c1Array=[]
let c2Array=[]
let c3Array=[]
let c4Array=[]
bigArray.forEach((item,index)=>{
  let items=Object.keys(item)
  if(items.length==6){
    c1Array.push(item)
  }
  if(items.length==8){
    c2Array.push(item)
  }
  if(items.length==10){
    c3Array.push(item)
  }
})

```

```

    }
    if(items.length==12){
        c4Array.push(item)
    }
})
console.log(c1Array)
console.log(c2Array)
console.log(c3Array)
console.log(c4Array)

let obj = {
    "content":[

    ]
}
c1Array.forEach(item=>{
    if(item.c1 == 1){
        let c1 = 1
        let newitem = {}
        newitem.str = item.c1str
        newitem.value = item.value
        newitem.limit = item.limit
        newitem.items = []
        c2Array.forEach(item2=>{
            let newitem2 = {}
            if(item2.c1 == c1){
                newitem2.str = item2.c2str
                newitem2.value = item2.value
                newitem2.limit = item2.limit
                newitem.items.push(newitem2)
            }
        })
        obj.content.push(newitem)
    }else if(item.c1 == 3){
        let c1 = 3
        let newitem = {}
        newitem.str = item.c1str
        newitem.value = item.value
        newitem.limit = item.limit
        newitem.items = []
        c2Array.forEach(item2=>{
            let newitem2 = {}
            if(item2.c1 == c1){
                newitem2.str = item2.c2str
                newitem2.value = item2.value
                newitem2.limit = item2.limit
                newitem.items.push(newitem2)
            }
        })
        obj.content.push(newitem)
    }
})
console.log(obj)

</script>
</body>
</html>

```

